

TEST REPORT

June 17, 2024

Stewart Hunter
325 Eastern Valley Way,
MIDDLE COVE NSW 2068

Your Reference: 325 Eastern Valley Way, Middle Cove
Job Number: 73676

Attention: Stewart Hunter

Dear Stewart,

In accordance with your instructions, Airsafe tested samples from the above site for asbestos content.

The following samples were processed on the dates indicated.

Samples:	2 Fibrous Insulation Samples
Date of Sample Receipt:	17/06/24
Date of Sample Analysis:	17/06/24
Date of Preliminary Report Sent:	Not Issued

The results are contained in the following pages of this report.

Should you have any queries regarding this report please contact the undersigned.

Yours faithfully
AIRSAFE LABORATORIES PTY LTD



Matthew Shaw
Approved Identifier and Signatory

PROJECT: 325 Eastern Valley Way, Middle Cove

JOB NO: 73676

Sample No	Location/Reference	Sample Description	Asbestos ID - Material
73676-1	Insulation - white	34g fibrous insulation	No asbestos detected, Synthetic mineral fibres detected
73676-2	Insulation - yellow	5g fibrous insulation	No asbestos detected, Synthetic mineral fibres detected

Method: Samples have been analysed using polarised light microscopy including dispersion staining in accordance with the AS 4964 – 2004 Method for the qualitative identification of asbestos in bulk samples and in-house method AS102 - Method for the Qualitative Identification of Asbestos in Bulk Samples.

Sampling: Samples have been analysed on an “as received” basis.

Location of Laboratory Activities: Level 1, 488 Botany Road, Beaconsfield NSW 2015 Australia.

Comment: Even after disintegration of certain bulk samples (vinyl tiles and bituminous type materials), the detection of fibres may be difficult when using Polarised Light Microscopy and Dispersion Staining Techniques. This may be due to the matrix of the sample (uneven distribution), or fine fibres that are difficult to detect and positively identify.

Disclaimer: Approximate sample weights and size only – not covered as part of the scope of accreditation.

Note: The results relate only to the samples tested.

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.

Airsafe shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Airsafe be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report.

Any other holder of this document is advised that information contained hereon reflects Airsafe’s findings at the time of its intervention only and within the limits of Client’s instructions, if any. The Airsafe’s sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.



This document is issued in accordance with NATA’s accreditation requirements.
Accredited for compliance with ISO/IEC 17025 – Testing.
NATA accredited laboratory 2959.
This report must not be reproduced except in full