

Inspection Report

Provided By



Profile building and pest inspections

12/1 Bondi Ave, Mermaid Beach, Queensland, 4218
P 0478181208
gregpalmer17@hotmail.com

Inspection Address

4 Woodstock Ct Parkwood , Gold Coast , QLD



Report Information

Client Information

Client Name	Jason And Demelza Griffin
Report Ordered By	Kate Hitchings
Email	jasondemelza1@bigpond.com

Inspection Information

Report/Agreement #	1108260845021156
Inspection Date:	11 Aug 2026
Inspection Time:	09:00 am

Pest And Building Inspection

The Scope of the Inspection: This report Complies with Australian Building Standards AS 4349.1-2007. Inspection of Buildings Part 1: Pre- Purchase Inspections-Residential Buildings- Appendix "C" and with AS 4349.3-2010 (Visual Timber Pest Inspection Report)

Only the name at the front page of the report "Client" should rely on this report. If this report has been issued to you by anyone you must not rely on this report as a pre purchase building and pest inspection report. You are not to rely on its findings or contents and seek to obtain your own independent pre purchase inspection report as this report or its contents is non transferable. The inspection WILL NOT report on items listed in Appendix "D" of AS43491.2007.

If the property is part of a Strata or Company Title , then Appendix "B" of the Australian Standards applies.

Special Requirements: Unless stated otherwise in the report It is acknowledged that there are no special requirements placed on this inspection that are outside the scope of the abovementioned Australian Standard.

Inspection Agreement: This report is subject to the terms, scope, description and limitations of the inspection agreement that was entered into prior to the inspection being performed. (Note: This agreement may have been entered into by your Solicitor/Conveyancer or other agent). If you are unsure in any way as to how that inspection agreement impacts this inspection and report, please seek clarification prior to committing to the property.

Changes to the Inspection Agreement: Unless stated otherwise in the report It is acknowledged that if any inspection agreement is in place in respect to this inspection, no changes have been made between the scope of the pre-Inspection Agreement and the scope of this inspection report.

Please read the entire report. Refer to the terms & conditions as they form part of the report

Areas to be Inspected and Restrictions

The Dwelling and the site including fencing that is up to 30 meters from the building and within the boundaries of the site. Where present and accessible, the Inspection shall include. (Except where the dwelling is part of a Strata Complex, then it will only be the individual dwelling and it's immediate surrounds

- (a) The interior of the building.
- (b) The roof space.
- (c) The exterior of the building
- (d) The sub-floor space
- (e) The roof exterior
- (f) The property within 30 m of the building subject to inspection.

Restrictions may apply to the above. See areas where full access is restricted

Visual Inspection Only

This is a visual inspection only limited to those areas and sections of the property fully accessible and visible to the inspector on the date of inspection. The inspection did not include breaking apart, dismantling, removing or moving objects including, but not limited to, foliage, mouldings, roof insulation/ sisalation, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances or personal possessions. The inspector cannot see inside walls, between floors, inside skillion roofing, behind stored goods in cupboards and other areas that are concealed or obstructed. The inspector did not dig, gouge, force or perform any other invasive procedures. Visible timbers cannot be destructively probed or hit without the written permission of the property owner.

Very Important note to the purchaser.

In the event that areas where access is restricted or not accessed structural defects, termite damage or activity may be present but not seen. Access should be provided and a follow up or re-Inspection should take place. Please consult with the vendor and request full access to restricted areas. This should be done prior to a decision to purchase.

Table of Contents



1. 1). PROPERTY AND INSPECTION INFORMATION



2. 2). SITE



3. 3). EXTERIOR



4. 7). INTERIORS.



5. 8). KITCHEN & LAUNDRY.



6. 9). BATHROOM(S).



7. 11). ROOF VOID.



8. 13). ROOF, GUTTER AND DOWNPIPES



9. 16). CONCLUSION



10. 19). TIMBER PEST ACCESS AND RESTRICTIONS



11. 20). TIMBER PEST FINDINGS



12. 21). CONDUCTIVE CONDITIONS



13. 22). OVERALL ASSESSMENT

Summary Of Major Defects And Safety Hazards

Below is a summary of significant items requiring immediate action.

The # denotes to the defect number in the report

Section	Location	Name	Comment
2). SITE	Trees	Tree Findings	#6. Large plant base is in close proximity to the building can cause problems with the building foundations, blocking gutters and underground plumbing. Removing of trees or installing a root barrier may be required. Recommend contacting an experienced arborist for further clarification on this matter
3). EXTERIOR	Exterior Walls	Condition	#8. Brick mortar has deteriorated in Several areas At rear of house. Can affect the integrity of the brick wall.. Contact a licensed bricklayer for repairs.
7). INTERIORS.	Garage	Ceiling	#14. Ceiling and wall water stains above garage door - No moisture readings obtained. Recommendations: leaks likely to return unless repairs have been carried out -Hidden damage may be present or can occur if left unattended. Contact a licensed Roofing contractor for further evaluation and repair as necessary. Patch and paint defect as required
7). INTERIORS.	Garage	Ceiling	#16. Ceiling sagging in areas - Requires repairs to prevent further collapse - Recommendations: Contact a licensed plasterer for further advice and repairs.
7). INTERIORS.	Dining room	Ceiling	#23. Ceiling water stains - No moisture readings obtained. Recommendations: leaks likely to return unless repairs have been carried out -Hidden damage may be present or can occur if left unattended. Contact a licensed Roofing contractor for further evaluation and repair as necessary. Patch and paint defect as required
11). ROOF VOID.	Insulation	Insulation	#37. Insufficient spacing between down lights to insulation and/or timbers. This poses a fire risk. Contact a licensed Electrician for repairs urgently
16). CONCLUSION	Condition Of Inspected Structure	The incidence of Major Defects	#42. The incidence of major defects in this residential Dwelling as compared with similar Dwellings of age and type is considered TYPICAL. It is strongly recommended to obtain quotes for repair of any of the defects noted before contract becomes binding. A major defect is defined as /: A defect of sufficient magnitude where rectification has to be carried out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.
16). CONCLUSION	Condition Of Inspected Structure	The incidence of Major Defects	#43. Please note that the summary is not the report and the report MUST be read in full

Summary Of Minor Defects

Below is a summary of defects other than Major defects.

The # denotes to the defect number in the report

Section	Location	Name	Comment
2). SITE	Driveway	Driveway Condition	#1. Large cracking detected to driveway. Recommend to Contact a licensed Concretor for further advice on repairs
2). SITE	Paths	Pathways Condition	#2. Common cracks and settlement were observed on paths. Recommend to monitor for any changes and contact a licensed concretor for repairs as needed.
2). SITE	Fences & Gates	Overall Condition	#3. Fences are leaning over moderately in some areas. Recommend to contact a licensed contractor to repair any leaning sections as necessary
2). SITE	Fences & Gates	Overall Condition	#4. fences are leaning over slightly in some sections. Recommend to contact a licenced contractor to Repair any sections as necessary
2). SITE	Retaining Walls	Overall Condition	#5. Brick/block retaining walls have typical cracking to them. Recommend to monitor for any changes and to contact a licensed bricklayer for further advice and repairs as necessary
2). SITE	Other site defects	Other site defects	#7. Pergola is not bolted down and could blow away in strong wind
3). EXTERIOR	Exterior Walls	Condition	#9. Minor cladding damage at rear Gable
3). EXTERIOR	Eaves	Eave Condition	#10. Eave trim detached In a few areas. Contact a licensed carpenter for advice and repairs.
3). EXTERIOR	Garage doors	Garage door	#11. Minor rust/damage to bottom corners of garage door where is rubbing against the brickwork?
3). EXTERIOR	Other exterior defects	Other exterior defects	#12. Timber slats loose on pool filter cover
7). INTERIORS.	Internal Areas	Flooring	#13. Some chips to floor tiles. Cosmetic damage only. Repair as necessary
7). INTERIORS.	Garage	Ceiling	#15. Poor butt joint finish Visible under normal light conditions. Contact a licensed plasterer for further assistance and advise on repairs
7). INTERIORS.	Garage	Flooring	#17. Common cracking to Garage floor. This is very common of Garage floors and is generally a cosmetic defect only. Recommend to monitor for any changes and seek further assistance if necessary
7). INTERIORS.	Garage	Flooring	#18. Salt staining entering through exterior wall. This is common of the wetting and drying of concrete. In severe cases damage to concrete can occur. Recommend to contact a licensed concretor for further assistance
7). INTERIORS.	Hallway	Ceiling	#19. Typical settlement cracking sighted. Contact a licensed plasterer for further advice and repair

7). INTERIORS.	Hallway	Ceiling	#20. Cracking to ceiling hallways. Recommend the installation of an expansion joint. Contact a licensed plasterer for further advice on this matter
7). INTERIORS.	Living room	Ceiling	#21. Poor butt joint finish Visible under normal light conditions. Contact a licensed plasterer for further assistance and advise on repairs
7). INTERIORS.	Living room	External doors	#22. Damage or tears to some fly screens. Repairs recommended
7). INTERIORS.	Dining room	Windows	#24. Some Windows are difficult to open and close. Maintenance to rolling/ sliding mechanism required. Contact a window repair company for repairs.
7). INTERIORS.	Dining room	External doors	#25. Some external Sliding Doors are difficult to open and close. Maintenance to rolling/ sliding mechanism recommended
7). INTERIORS.	Bedroom 4	Robe/linen doors	#26. Sliding doors were not operating correctly on day of inspection. Maintenance required
8). KITCHEN & LAUNDRY.	Kitchen	Cupboards And Bench Tops	#27. Poor finish around sink where cut out was wrong size.
8). KITCHEN & LAUNDRY.	Laundry	Floor	#28. Minor cracks floor tiles. A qualified tiler should be engaged for repairs.
9). BATHROOM(S).	Main Ensuite	Shower	#29. Shower head is leaking. A qualified plumber should be engaged for advice and recommendations.
9). BATHROOM(S).	Main Ensuite	Shower	#30. Cracked tiles to shower hob. Contact a licensed Tiler for repairs.
9). BATHROOM(S).	Main Ensuite	Flooring	#31. Cracked floor tiles detected. Recommend contacting a licensed for Tiler for further advice on this matter
9). BATHROOM(S).	Main Ensuite	Vanity	#32. Some minor cosmetic damage to sections of vanity
9). BATHROOM(S).	Bathroom	Shower	#33. Cracked tiles to shower hob. Contact a licensed Tiler for repairs.
9). BATHROOM(S).	Bathroom	Flooring	#34. Some Drummy floor tiles detected. No evidence of lifting or cracking. Recommend to monitor the area for any changes and proceed with repairs as necessary
9). BATHROOM(S).	Bathroom	Ceiling	#35. Settlement Cracks Noted . These are typical and generally patch and paint will suffice,
9). BATHROOM(S).	Bathroom	Vanity	#36. Some minor cosmetic damage to sections of vanity
13). ROOF, GUTTER AND DOWNPIPES	Roof Covering	Roof Condition (tile)	#38. Paint has deteriorated to several areas of the roof. Seek further advice from a roof restoration contractor as necessary
13). ROOF, GUTTER AND DOWNPIPES	Roof Covering	Roof Condition (tile)	#39. The corners of some roof tiles have been cracked off. It is recommended to have these repaired to prevent any possible chance of leaks occurring. Contact a licensed roof tile for repairs.

13). ROOF, GUTTER AND DOWNPIPES	Guttering	Gutter Findings	#40. There is evidence of leaking gutter joins. Silicone requires repairs. Contact a roof plumber for advice and repairs.
13). ROOF, GUTTER AND DOWNPIPES	Down Pipes	Down Pipe Findings	#41. Leaking down pipe joins visible. Recommendations: A qualified roof plumber should be engaged to repair.
16). CONCLUSION	Condition Of Inspected Structure	Incidence of Minor Defects. (This list is not definitive and other minor defects are likely present. It is to give an indication of the property's overall condition)	#44. The incidence of minor defects in this residential Dwelling as compared with similar Dwellings of age and type is considered TYPICAL . It is strongly recommended to obtain quotes for repair of any of the defects noted before contract becomes binding.
16). CONCLUSION	Condition Of Inspected Structure	Incidence of Minor Defects. (This list is not definitive and other minor defects are likely present. It is to give an indication of the property's overall condition)	#45. Please note that the summary is not the report and the report MUST be read in full



1). PROPERTY AND INSPECTION INFORMATION

Weather at Inspection Area

Weather Conditions

The weather was Dry at the time of the building inspection.

Property Information

Building Type

The dwelling is a Residential House.

Construction Type

Brick Verneer wall cladding present

Timber framed construction present

Roof Cladding

Tile roofing

Roof Design

truss roof design present

Floor design

Slab On Ground Construction.

Storeys

Single level dwelling

Property Occupied

The property was not occupied. Where building is unoccupied an accurate assessment of moisture may not be possible

Property Furnished

The home was Not Furnished.

People Present

No persons Present at Inspection.

Areas Where Full Inspection Restricted (applies to Timber Pest Inspection also).

Interior

Inspection restricted due to, but not limited to floor coverings, built in sections, wall and ceiling linings, voids in built in cupboards, cavity walls, Flooring systems, bathtubs and ducts etc.

Inspection restricted due to window furnishings










Interior (continued)

Inspection restricted due to floor coverings, built in sections, wall and ceiling linings, voids in built in cupboards, bathtubs and ducts.

Inspection restricted due to window furnishings






Roof surface

Solar panels restricted visual inspection

Roof area



Roof void

Visual inspection restricted to eaves due to design

Visible inspection was restricted to low or tight access to areas in roof void due to the design of the roof

Visible inspection restricted due to ceiling batts

Inspection restricted due to storage



Fences

Inspection conducted from inside of the fence line only

Retaining walls

Inspection restricted to visual sections only

Visual Inspection conducted from inside the Boundary fences only

Subfloor

No access to subfloor where slab on ground construction

Site conditions.

Site conditions





Undetected Structural Damage Risk Assessment

Moderate Risk

A further inspection is strongly recommended of areas that were not readily accessible, and of inaccessible or obstructed areas once access has been provided or obstruction removed. This may require the moving, lifting or removal of obstructions such as floor coverings, furniture, stored items, foliage and insulation. In some instances, it may also require the removal of ceiling and wall linings, and the cutting of traps and access holes. This recommendation should be implemented as soon as possible. For further advice consult your Building Inspector.

Utility Status

Water

The water was Connected. All plumbing pipe installation should be assessed by a licensed plumber.

Electricity

There was no electrical connection at the time of the inspection. This may mean the mains have only been switched off or that re-connection with a supplier is required. We do not attempt to activate power at the dwelling. Note: We do not carry out electrical inspections for wiring or safety. This must be, by law, carried out by a licensed electrician and I recommend you have all electrical wiring and components assessed by a licensed electrician.

inspection Agreement

Were there any specific requirements to The Pre Inspection Agreement

No specific requirements to the Inspection or Pre inspection Agreement were requested by the client or their representatives.



2). SITE

Driveway

Driveway Condition


#1. Large cracking detected to driveway. Recommend to Contact a licensed Concretor for further advice on repairs



Paths

Pathways Condition

#2. Common cracks and settlement were observed on paths. Recommend to monitor for any changes and contact a licensed concretor for repairs as needed.



Fences & Gates

Overall Condition

#3. Fences are leaning over moderately in some areas. Recommend to contact a licensed contractor to repair any leaning sections as necessary

#4. fences are leaning over slightly in some sections. Recommend to contact a licenced contractor to Repair any sections as necessary



Retaining Walls

NOTE

As per Section 3.21 and appendix C6 of Australian Standards AS4349.1-2007 only retaining and landscaping walls over 700mm high require to be inspected.

Retaining walls that are not visible from accessible areas (generally within the property boundaries) have not been inspected. Permission from adjoining properties should be obtained for these areas to be inspected.

Overall Condition

#5. Brick/block retaining walls have typical cracking to them. Recommend to monitor for any changes and to contact a licensed bricklayer for further advice and repairs as necessary



Surface Drainage

Drainage Findings

Note # It is often difficult to ascertain in dry conditions if site drainage is adequate and it is therefore recommended that you assess after a rainfall period to be able to sufficiently ascertain if any problems exist in this regard. If water is ponding around perimeter walls and paths or appears to be flowing into the footings/ foundations you must have assessed by a qualified plumber or landscaper.

Trees

Tree Findings

#6. Large plant base is in close proximity to the building can cause problems with the building foundations, blocking gutters and underground plumbing. Removing of trees or installing a root barrier may be required. Recommend contacting an experienced arborist for further clarification on this matter

please note: If any Mature trees are in close proximity to the building they can cause problems with the building foundations, blocking gutters and underground plumbing. Recommend contacting an experienced arborist for further clarification on this matter to see if a root barrier or removal of trees is recommended



Other site defects

Other site defects

#7. Pergola is not bolted down and could blow away in strong wind






3). EXTERIOR

Exterior Walls

Condition

#8. Brick mortar has deteriorated in Several areas At rear of house. Can affect the integrity of the brick wall.. Contact a licensed bricklayer for repairs.

#9. Minor cladding damage at rear Gable



Eaves

Eave Condition

#10. Eave trim detached In a few areas. Contact a licensed carpenter for advice and repairs.



Garage doors

Garage door

#11. Minor rust/damage to bottom corners of garage door where is rubbing against the brickwork?



Other exterior defects

Other exterior defects

#12. Timber slats loose on pool filter cover





7). INTERIORS.

Internal Areas

Windows

A couple of Flyscreens not installed



Flooring

#13. Some chips to floor tiles. Cosmetic damage only. Repair as necessary




Garage

Ceiling

#14. Ceiling and wall water stains above garage door - No moisture readings obtained. Recommendations: leaks likely to return unless repairs have been carried out -Hidden damage may be present or can occur if left unattended. Contact a licensed Roofing contractor for further evaluation and repair as necessary. Patch and paint defect as required

#15. Poor butt joint finish Visible under normal light conditions. Contact a licensed plasterer for further assistance and advise on repairs

#16. Ceiling sagging in areas - Requires repairs to prevent further collapse - Recommendations: Contact a licensed plasterer for further advice and repairs.



Flooring

#17. Common cracking to Garage floor. This is very common of Garage floors and is generally a cosmetic defect only. Recommend to monitor for any changes and seek further assistance if necessary

#18. Salt staining entering through exterior wall. This is common of the wetting and drying of concrete. In severe cases damage to concrete can occur. Recommend to contact a licensed concreter for further assistance



Hallway

Ceiling

#19. Typical settlement cracking sighted. Contact a licensed plasterer for further advice and repair

#20. Cracking to ceiling hallways. Recommend the installation of an expansion joint. Contact a licensed plasterer for further advice on this matter



Living room

Ceiling

#21. Poor butt joint finish Visible under normal light conditions. Contact a licensed plasterer for further assistance and advise on repairs



External doors

#22. Damage or tears to some fly screens. Repairs recommended



Dining room

Ceiling

#23. Ceiling water stains - No moisture readings obtained. Recommendations: leaks likely to return unless repairs have been carried out -Hidden damage may be present or can occur if left unattended. Contact a licensed Roofing contractor for further evaluation and repair as necessary. Patch and paint defect as required



Windows

#24. Some Windows are difficult to open and close. Maintenance to rolling/ sliding mechanism required. Contact a window repair company for repairs.



External doors

#25. Some external Sliding Doors are difficult to open and close. Maintenance to rolling/ sliding mechanism recommended



Bedroom 4

Robe/linen doors

#26. Sliding doors were not operating correctly on day of inspection. Maintenance required





8). KITCHEN & LAUNDRY.

Kitchen

Cupboards And Bench Tops

#27. Poor finish around sink where cut out was wrong size.



Laundry

Floor

#28. Minor cracks floor tiles. A qualified tiler should be engaged for repairs.





9). BATHROOM(S).

Main Ensuite

Shower

#29. Shower head is leaking. A qualified plumber should be engaged for advice and recommendations.

#30. Cracked tiles to shower hob. Contact a licensed Tiler for repairs.



Flooring

#31. Cracked floor tiles detected. Recommend contacting a licensed for Tiler for further advice on this matter



Vanity

#32. Some minor cosmetic damage to sections of vanity



Important Disclaimer

Refer to Section 7 of the Terms And conditions section of this report

Bathroom

Shower

#33. Cracked tiles to shower hob. Contact a licensed Tiler for repairs.



Flooring

#34. Some Drummy floor tiles detected. No evidence of lifting or cracking. Recommend to monitor the area for any changes and proceed with repairs as necessary



Ceiling

#35. Settlement Cracks Noted . These are typical and generally patch and paint will suffice,

**Vanity**

#36. Some minor cosmetic damage to sections of vanity





11). ROOF VOID.

Insulation

Insulation

#37. Insufficient spacing between down lights to insulation and/or timbers. This poses a fire risk. Contact a licensed Electrician for repairs urgently





13). ROOF, GUTTER AND DOWNPIPES

Roof Covering

General Disclaimer

Refer to Section 2C of the Terms And Conditions section of this report

Roof Condition (tile)

#38. Paint has deteriorated to several areas of the roof. Seek further advice from a roof restoration contractor as necessary


#39. The corners of some roof tiles have been cracked off. It is recommended to have these repaired to prevent any possible chance of leaks occurring. Contact a licensed roof tile for repairs.



Guttering

Gutter Findings

#40. There is evidence of leaking gutter joins. Silicone requires repairs. Contact a roof plumber for advice and repairs.



Down Pipes

Down Pipe Findings

#41. Leaking down pipe joins visible. Recommendations: A qualified roof plumber should be engaged to repair.





16). CONCLUSION

Condition Of Inspected Structure

NOTE

Please note. NO INSPECTION WAS CARRIED OUT TO THE FOLLOWING Any Electrical appliances, smoke alarms, ceiling fans, pool equipment, garage door motors, lights, Switches, Pumps, Air conditioning, solar Installations ETC. Strongly recommend having any and all of the above checked by a licenced electrical contractor. **Any comment made on any of the above is purely an observation and not a proper inspection or test, and defects and faults may still be present. It is the purchasers responsibility to ensure all electrical installations etc are working correctly**

Overall Condition

The overall condition of this Dwelling has been compared to similar constructed buildings of approximately the same age where those buildings have had a maintenance program implemented to ensure that the building members are still fit for purpose.

The summary lists of Major and Minor defects included this report are the opinion of the inspector, other inspectors or individuals may have a different opinion to what is a Minor or a Major Defect

The incidence of major and minor defects and overall condition in this residential Dwelling as compared with similar Dwellings is listed below.

Please refer to the **TERMS AND CONDITIONS** section of this report for definition

Any photos identifying defects are to help identify the defect and are not to give an indication of the extent of the defect and further extent of the defect is likely.

The incidence of Major Defects

#42. The incidence of major defects in this residential Dwelling as compared with similar Dwellings of age and type is considered **TYPICAL**. **It is strongly recommended to obtain quotes for repair of any of the defects noted before contract becomes binding.** A major defect is defined as /: A defect of sufficient magnitude where rectification has to be carried out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.

#43. Please note that the summary is not the report and the report **MUST** be read in full

Incidence of Minor Defects. (This list is not definitive and other minor defects are likely present. It is to give an indication of the property's overall condition)

#44. The incidence of minor defects in this residential Dwelling as compared with similar Dwellings of age and type is considered **TYPICAL** . **It is strongly recommended to obtain quotes for repair of any of the defects noted before contract becomes binding.**

#45. Please note that the summary is not the report and the report **MUST** be read in full

The Overall Condition Of This Dwelling

The overall condition of this residential dwelling in the context of its age, type and general expectations of similar properties is **Typical**

Safety Switch

A safety switch was cited but is not checked or tested.



Asbestos

Note. Any Dwelling built before mid 1980's is highly likely to have asbestos containing material. Any Dwelling built before 1990 may likely have asbestos containing material.

See the following webpage for further Information

[https://www1.health.gov.au/internet/publications/publishing.nsf/Content/asbestos-toc/\\$FILE/asbestos-feb13.pdf](https://www1.health.gov.au/internet/publications/publishing.nsf/Content/asbestos-toc/$FILE/asbestos-feb13.pdf)

Solar panels

Solar panels sighted. The solar system was NOT tested during the inspection. it is strongly recommended that a licenced contractor specialising in Solar installations check the system for any defects or deficiencies.





17). TERMS AND CONDITIONS

The purpose of the inspection is to identify the major defects and safety hazards associated with the property at the time of the inspection. The inspection and reporting is limited to a visual assessment of structure in accord with AS 4349.1 appendix "C" or if not a pre-purchase report then the report complies with AS4349.0. This is a general appraisal only and cannot be relied on its own, a further inspection by specialist and qualified trades is strongly recommended.

NOT A PEST REPORT: This inspection and report will not inspect, seek or attempt to identify timber pest activity or damage. We strongly recommend you obtain a timber pest inspection conducted by a licensed and suitably qualified pest inspector. IF THIS REPORT IS PART OF A BUILDING AND PEST INSPECTION; please see timber pest report below.

DEFINITIONS AND TERMINOLOGY

SERVICEABLE: The building material or component is in reasonable or serviceable condition for the age of the dwelling.

TRADESMAN: A defect or a number of defects were visible that will require assessment by a qualified trades person.

AGE: The component has deterioration due to ageing or lack of upkeep and or maintenance.

MONITOR: Some defects may require monitoring to ascertain if the defect will worsen, reappear or cause further problems.

STRATA: In the case of strata and company title properties, the inspection is limited to the interior and immediate exterior of the particular unit being inspected report.

HIGH: The frequency and/or magnitude of defects are beyond the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

TYPICAL: The frequency and/or magnitude of defects are consistent with the inspector's expectations when compared to similar buildings of approximately the same age which have been reasonably well maintained.

LOW: The frequency and/or magnitude of defects are lower than the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

ABOVE AVERAGE: The overall condition is above that consistent with dwellings of approximately the same age and construction. Most items and areas are well maintained and show a reasonable standard of workmanship when compared with buildings of similar age and construction.

AVERAGE / TYPICAL The overall condition is consistent with dwellings of approximately the same age and construction. There will be areas or items requiring some repair or maintenance.

BELOW AVERAGE: The Dwelling and its parts show some significant defects and/or very poor non- tradesman like workmanship and/or long-term neglect and/or defects requiring major repairs or reconstruction of the major Dwelling.

SIGNIFICANT ITEMS: An item that must be reported in accordance with the scope of the inspection.

MAJOR DEFECT: A defect of sufficient magnitude where rectification has to be carried out in order to avoid unsafe conditions, loss of utility or further deterioration to the property.

MINOR DEFECT: Any defect other than what is described as a Significant Item or major defect.

SAFETY HAZARD: A defect that presents unsafe conditions and must be reported as a Major defect.

ACCESSIBLE AREA: Is any area of the property and structures allowing the inspector safe and reasonable access within the scope of the inspection.

LIMITATION: A factor that prevents full or proper inspection of the Dwelling.

IMPORTANT INFORMATION

Important information regarding the scope and limitations of the inspection and this report. Any person who relies upon the contents of this report does so acknowledging that the following clauses, which define the scope and limitations of the inspection, form an integral part of the report. The inspection comprised a visual assessment of the property to identify major defects and to form an opinion regarding the general condition of the property at the time and date of the visual inspection. An estimate of the cost of rectification of defects is outside the scope of Australian Standard AS 4349 and does not form part of this report. If the property inspected is part of a Strata or Company Title, then the inspection is limited to the interior and the immediate exterior of that particular residential dwelling. The inspection does not cover common property. This report and any other attached report should not be relied upon if the contract for sale becomes binding more than 30 days after the date of initial inspection. A re-inspection after this time is essential. Further, this report is not intended to be used as a marketing tool by and real-estate agents and only the person named in the CLIENT INFORMATION section of the report shall this report apply to as it is assumed and agreed that the person who orders the report is indeed the person purchasing the property inspected. Where a report is ordered on behalf of a CLIENT it is assumed that the terms and condition and Pre Inspection Agreement have been fully explained to the CLIENT by the person or company ordering the report.

We strongly advise that any cracking reported in this report should be referred to a structural engineer for further assessment and advice. Please refer to Cracking Of Building Elements in section 2G of these Terms And Condition

Acceptance Criteria: The Dwelling shall be compared with a Dwelling that was constructed in accordance with the generally accepted practice at the time of construction and which has been maintained such that there has been no significant loss of strength and serviceability.

Limitations: This report is limited to a visual inspection of areas where safe and reasonable access is available and access permitted on the date and at the time of inspection. The Inspection will be carried out in accordance with AS4349.1-2007. The purpose of the inspection is to provide advice to a prospective purchaser regarding the condition of the property at the date and time of inspection. Areas for Inspection shall cover all safe and accessible areas. It does not purport to be geological as to foundation integrity or soil conditions, engineering as to structural, nor does it cover the condition of electrical, plumbing, gas or motorised appliances. It is strongly recommended that an appropriately qualified contractor check these services prior to purchase. As a matter of course, and in the interests of safety, all prospective purchasers should have an electrical report carried out by a suitably qualified contractor. This report is limited to (unless otherwise noted) the main structure on the site and any other building, structure or outbuilding within 30m of the main structure and within the site boundaries including fences.

Safe and Reasonable Access: Only areas to which safe and reasonable access is available were inspected. The Australian Standard AS4349.1 or AS4349.0 defines reasonable access as "areas where safe, unobstructed access " is provided and the minimum clearances specified below are available, or where these clearances are not available, areas within the inspector's unobstructed line of sight and within arm's length. Reasonable access does not include removing screws and bolts to access covers. Reasonable access does not include the use of destructive or invasive inspection methods and does not include cutting or making access traps or moving heavy furniture, floor coverings or stored goods.

Roof Interior- Access opening 400 x 500 mm - Crawl Space 600 x 600mm - Height accessible from a 3.6m ladder.

Roof Exterior- Must be accessible from a 3.6m ladder placed on the ground.

1) NOT A CERTIFICATE OF COMPLIANCE: This report is not an all-encompassing report dealing with the building from every aspect. It is a reasonable attempt to identify any obvious or significant defects apparent at the time of the inspection. Whether or not, a defect is considered significant or not depends too a large extent, upon the age and type of the Dwelling inspected. This report is not a certificate of compliance with the requirements of any act, regulation, ordinance or by-law. It is not a structural report. Should you require any advice of a structural nature you should contact a structural engineer.

2) VISUAL INSPECTION: This is a visual inspection only limited to those areas and sections of the property safe that are fully accessible safe to access and visible to the inspector on the date of inspection.

2A) Please refer to each individual area regarding sections that were incapable or being inspected. Please acknowledge the following. Where a complete inspection of some areas listed through the report may not have been physically possible (due to but not limited to - storage, furniture, beds, personal belongings in cupboards and/or wardrobes, the 2nd storey roofing, gutters, fascia, flashings and the like, low clearance in sub floor or roof void areas, ducts and deep insulation restricting access in roof voids, sub floor restrictions including plumbing, ducts, low clearance, no access doors or access doors too small and the like) then it follows that defects, timber pest activity and/or damage may exist in these areas. To adequately inspect these restricted areas, ducts and floor boards may need to be removed, furniture moved, cupboards and wardrobes emptied which will be difficult to carry out. This will obviously be difficult to carry out due to time restrictions and permission would need to be obtained from the property owner.

This Firm DOES NOT GUARANTEE IN ANY WAY that there ARE OR ARE NOT any defects, termite damage or live termites in any areas not inspected. To obtain a full understanding of the report findings, it is essential you read the entire inspection report, including the information sections at the end of this report and I encourage you to call me if you have any queries at all before purchasing the inspected dwelling.

2B) Entering attics or roof voids that are insulated can cause damage to the insulation and attic framing. Attics with deep insulation cannot be safely inspected due to limited visibility of the framing members upon which the inspector must walk. In such cases, the attic is only partially accessed, thereby limiting the review of the attic area from the hatch area only. Inspectors will not crawl the attic area when they believe it is a danger to them or that they might damage the attic insulation or framing. There is a limited review of the attic area viewed from the hatch only in these circumstances.

Roof Space Access – only if inspector can turn off power. Queensland Legislation Compliance From 1 January 2025, new requirements introduced under Queensland legislation regulate access to domestic roof spaces. Where applicable, the inspector will comply with all relevant safety protocols as mandated by this legislation. If safe access, supervision, or necessary isolation procedures cannot be confirmed or implemented at the time of inspection, entry into the roof space may be refused. The client acknowledges that such access limitations are outside the control of the inspector and the "client/You" agree that **no liability will be accepted for any defects or conditions not visible or accessible due to these legislative restrictions**.

2C) The roof covering will not be walked upon if in the opinion of the inspector it is not safe to do so. Generally issues that prevent roof access include, access height over 3 metres, steep pitch, wet/slippery surfaces, deteriorated covering. Not being able to walk a roof significantly limits our inspection, which can result in hidden defects going undetected. The overall condition of the roofing and its components is an opinion of the general quality and condition of the roofing material. The inspector cannot and does not offer an opinion or warranty as to whether the roof leaks or may be subject to future leakage. This report is issued in consideration of the foregoing disclaimer. The only way to determine whether a roof is absolutely watertight is to observe it during a prolonged rainfall. Many times, this situation is not present during the inspection. We offer no guarantee that the roof cladding or roof components such as flashing will not leak in the future.

2D) Limitations to the exterior inspection this is a visual inspection limited in scope by (but not restricted to) the following conditions: A representative sample of exterior components was inspected rather than every occurrence of components. The inspection does not include an assessment of geological, geotechnical, or hydrological conditions, or environmental hazards. Screening, shutters, awnings, or similar seasonal accessories, fences, recreational facilities, outbuildings, seawalls, break-walls, docks, erosion control and earth stabilization measures are not inspected unless specifically agreed-upon and documented in this report. Please note. If any wall cracking/cracks/openings are found at this dwelling, we cannot offer any guarantee that any visible wall cracks will not widen or lengthen over time or in the future as this is impossible to predict. We strongly recommend you contact a practicing structural engineer for further advice.

2E) Timber framed windows can bind or stick. This can be seasonal due to the fluctuation in moisture content in timber. If binding or sticking continues a carpenter may require adjustments. Binding windows is not normally a major defect, however in some circumstances binding windows and doors can be directly related to some differential footings settlement. If any timber fungal decay on frames or deteriorated putty seals is noted, the consultant will not attempt to operate windows due to potential damage. Windows that are sticking, binding or paint stuck will also not be forced open. Water leaks to windows and surrounds cannot be determined in the absence of rain.

2F) Internal Inspections. Carpets and or other floor coverings, cupboards/cabinets, joinery, finishes and fittings, normally obstruct inspection to the upper-side of flooring. Defects or timber pest damage may be present and not detected in areas where inspection was limited, obstructed or access was not gained. The condition of walls behind wall coverings, panelling and furnishings cannot be inspected or reported on. Only the general condition of visible areas is included in this inspection. Where fitted. Wood burning and other forms of fireboxes are outside the scope of this inspection. We recommend you have these tested prior to purchase for peace of mind.

2G) Cracking of Building Elements: Regardless of the type of crack(s) the inspector carrying out a visual inspection is unable to determine the expected consequences of the cracks. As a crack on the day can be 1mm wide but may have the potential to develop over time into structural problems for the home owner resulting in major expensive rectification work.

Information required to determine the consequences of a crack:

Nature of the foundation material on which the building is resting

- a) The design of the footings
- b) The site landscape and topography
- c) The history of the cracks

All these factors fall outside the scope of this inspection. However the information obtained from the items above are valuable in determining the expected consequences of the cracking and any remedial work.

Cracking Categories:

Cracking is also categorized into the following 5 categories with a description of typical damage and required repairs:

0-Hairline cracking, less than 0.1mm,

1-Fine cracks that do not need repair, less than 1.0mm,

2-Noticable cracks, yet easily filled 1mm - 5.0mm,

3-Cracks that can be repaired and possibly some of the wall sections will need to be replaced. Weather tightness can be impaired, 5.0mm -15.0mm,

4-Extensive repair works required involving breaking out and replacing these sections. Walls can become out of plumb and fall and causes reduced bearing capacity, 15.0mm - 25.0mm.

IMPORTANT: Regardless of location or size If cracks have been identified then a structural engineer is required to determine the significance of the cracking prior to a decision to purchase.

2H) Important Note: Where any elevated structure (deck, balcony, veranda etc.) is present, and this elevated structure is designed to accommodate people, you must have this structure checked by an engineer or other suitably qualified person. You should also arrange annual inspections of the structure by an engineer or other suitably qualified person to ensure any maintenance that may become necessary is identified. Care must be taken not to overload the structure. Nothing contained in this inspection should be taken as an indicator that we have assessed any elevated structure as suitable for any specific number of people or purpose. A qualified engineer can only do this. For the purpose of this report, the structure includes elevated decks; verandas, pergolas, balconies, handrails, stairs and children's play areas. Where any structural component is concealed by lining materials or other obstructions, these linings or obstructions must be removed to enable an evaluation to be carried out by an appropriately qualified person.

3) CONCEALED DEFECTS: This report does not and cannot make comment upon: Defects that may have been concealed the assessment or detection of defects (including rising damp and leaks) which may be subject to the prevailing weather conditions whether or not services have been used for some time prior to the inspection and whether this will affect the detection of leaks or other defects e.g. In the case of shower enclosures and bath tubs, the absence of any leaks or dampness at the time of the inspection does not necessarily mean that the enclosure will not leak after use) the presence or absence of timber pests; gas-fittings; common property areas; environmental concerns; the proximity of the property to flight paths, railways, or busy traffic; noise levels; health and safety issues; heritage concerns; security concerns; fire protection; site drainage (apart from surface water drainage); swimming pools and spas (non-structural); detection and identification of illegal building work; detection and identification of illegal plumbing work; durability of exposed finishes; neighbourhood problems; document analysis; electrical installation; any matters that are solely regulated by statute; any area(s) or item(s) that could not be inspected by the consultant.

4) NO GUARANTEE: Accordingly this report is not a guarantee that defects and/or damage do not exist in any inaccessible or partly inaccessible areas or sections of the property. Such matters may upon request be covered under the terms of a special purpose property report.

5) SWIMMING POOLS: Swimming pools/spas are not part of the standard building report under as4349.1-2007 and are not covered by this report. We strongly recommend a pool expert should be consulted to examine the pool and the pool equipment and plumbing as well as the requirements to meet the standard for pool fencing. Failure to conduct this inspection and put into place the necessary recommendations could result in finds for non-compliance under the legislation.

6) SURFACE WATER AND DRAINAGE: The retention of water from surface run off could have an effect on the foundation material which in turn could affect the footings to the house. Have water directed away from the house or to storm water pipes by a licensed drainage plumber. The general adequacy of site drainage is not included in the standard property inspection report. Comments on surface water drainage are limited as where there has been either little or no rainfall for a period of time; surface water drainage may appear to be adequate but then during periods of heavy rain, may be found to be inadequate. Any comments made in this report are relevant only to the conditions present at the time of inspection. It is recommended that a smoke test be obtained to determine any illegal connections, blocked or broken drains.

7) SHOWER RECESSES: All Shower areas are visually checked for leakage, but leaks often do not show except when the shower is in actual long-term use. Determining whether shower areas, bath/shower surrounds are watertight is beyond the scope of this inspection. It is very important to maintain adequate sealing in the bath areas. Very minor imperfections can allow water to get into the wall or floor areas and cause damage. Adequate and proper ongoing maintenance will be required in the future. Tests may be made on shower recesses to detect leaks (if water is connected). The tests may not reveal leaks or show incorrect waterproofing if silicone liquid or masonry sealant has been applied prior to the inspection. Such application is a temporary waterproofing measure and may last for some months before breaking down. The tests on the shower recesses are limited to running water within the recesses and visually checking for leaks as showers are only checked for a short period of time, prolonged use may reveal leaks that were not detected at the time of inspection. No evidence of a current leak during inspection does not necessarily mean that the shower does not leak.

8) GLASS CAUTION: Glazing in older Dwellings (built before 1978) may not necessarily comply with current glass safety standards AS1288. In the interests of safety, glass panes in doors and windows especially in trafficable areas should be replaced with safety glass or have shatterproof film installed unless they already comply with the current standard.

9) STAIRS AND BALUSTRADES: Specifications have been laid down by the National Construction Code Section 3.9 covering stairs, landings, balustrades to ensure the safety of all occupants and visitors in a Dwelling. Many balustrades and stairs built before 1996 may not comply with the current standard. You must upgrade all such items to the current standard to improve safety.

10) RETAINING WALLS: Where retaining walls are more than 700mm high these wall/s should have been installed with engineering design and supervision. Walls found on the site were not assessed and the performance of these walls is not the subject of a standard property report and should be further investigated with regard to the following items, adequate drainage systems, adequate load bearing, correct component sizing and batter.

11) ROOMS BELOW GROUND LEVEL: If there are any rooms under the house or below ground level (whether they be habitable or non-habitable rooms), these may be subject to dampness and water penetration. Drains are not always installed correctly or could be blocked. It is common to have damp problems and water entry into these types of rooms, especially during periods of heavy rainfall and this may not be evident upon initial inspection. These rooms may not have council approval. The purchaser should make his or her own enquiries with the Council to ascertain if approval was given.

12) ASBESTOS DISCLAIMER: No inspection for asbestos was carried out at the property and no report on the presence or absence of asbestos is provided.

13) MOULD (mildew and non-wood decay fungi) disclaimer: Mildew and non-wood decay fungi is commonly known as mould. However, mould and their spores may cause health problems or allergic reactions such as asthma and dermatitis in some people. No inspection for mould was carried out at the property and no report on the presence or absence of mould is provided.

14) MAGNESITE DISCLAIMER: No inspection for Magnesite flooring was carried out at the property and no report on the presence or absence of Magnesite flooring is provided. You should ask the owner whether Magnesite flooring is present and/or seek advice from a structural engineer.

15) ESTIMATING DISCLAIMER: No estimate is provided in this report. We strongly recommend you obtain quotes for repairs from licensed tradesman prior to a decision to purchase.

16) DISCLAIMER OF LIABILITY: No liability shall be accepted on an account of failure of the report to notify any problems in the area(s) or section(s) of the subject property physically inaccessible for inspection, or to which access for inspection is denied by or to the inspector (including but not limited to or any area(s) or section(s) so specified by the report) Compensation will only be payable for losses arising in contract or tort sustained by the client named on the front of this report. Compensation is limited to the price of the report initially paid by the claimant named in the report as the "CLIENT"

17) DISCLAIMER OF LIABILITY TO THIRD PARTIES: Compensation will only be payable for losses arising in contract or tort sustained by the Client named on the front of this report. Any third party acting or relying on this Report, in whole or in part, does so entirely at his or her own risk.

18) COMPLAINTS PROCEDURE: In the event of any dispute or claim arising out of, or relating to the Inspection or the Report, or any alleged negligent act or omission on Our part or on the part of the individual conducting the Inspection, either party may give written Notice of the dispute or claim to the other party.

OTHER RECOMMENDED INSPECTIONS

Electrical installation: All electrical wiring, meter-box and appliances need to be checked by a qualified electrician. The inspection of any electrical item is outside the scope of this report.

Plumbing: All plumbing including septic tanks need to be inspected and reported on by a plumber.

Hot water service: Hot water services need to be checked by a plumber and/or electrician.

Gas: All gas services need to be inspected and reported on by a gas plumber.

Phone: All phones, phone lines and outlets need to be inspected and reported on by a telecommunications technician.

Smoke Alarm: Australian standard AS3786 advises that smoke alarms are required for all buildings where people sleep. It is recommended that an electrician be consulted to give advice on those installed or to install smoke alarms.

Trees: Where trees are too close to the house this could affect the performance of the footing as the moisture levels change in the ground.

Contact the inspector: Please feel free to contact the inspector who carried out this inspection. Often it is very difficult to fully explain situations, problems, access difficulties, building faults or their importance in a manner that is readily understandable by the reader. Should you have any difficulty in understanding anything contained within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.



19). TIMBER PEST INSPECTION

Please note that this inspection and report was a Visual only inspection to the readily accessible areas of the property as defined within the terms and conditions of this report.

Please ensure that you read all sections of the report as well as the additional information at the rear of Please note that this inspection and report was a Visual only inspection to the readily accessible areas of the property as defined within the terms and conditions of this report. As this is a visual inspection only there may be damage to structural timbers within the Dwelling from termite infestation which is concealed by wall/s and or ceiling linings, and that such damage has neither been inspected for nor reported herein. Please ensure that you read all sections of the report as well as the additional information at the rear of the report and understand the limitations and the special recommendations for this construction style. If there is something you do not understand or require further clarification. Please contact the Inspector. **IMPORTANT: The Client acknowledges that, unless stated otherwise, the Client, as a matter of urgency should implement any recommendation or advice given in this report. Please contact the inspector If there is something you do not understand or require further clarification on.**



19). TIMBER PEST ACCESS AND RESTRICTIONS

Note

Inspection Information

For the purpose of visual timber pest inspection this timber pest inspection report which form part of a combined timber pest and building inspection. The inspection information listed at the beginning of the building inspection report namely report information shall apply. Including the date and time of inspection, who the report is prepared for and the description of the property inspected. **THIS IS A VISUAL INSPECTION ONLY** in accord with the requirements of AS4349.3-2010 - Inspection of buildings Part 3: Timber Pest Inspections.

Where a property is furnished at the time of the inspection then you must understand that the furnishings and stored goods may be concealing evidence of timber pest activity. This evidence may only be revealed when the property is vacated. A further inspection of the vacant property is strongly recommended if this is the case.

No inspection was made and no report is submitted, of inaccessible areas. If a complete inspection of the areas in the dwelling was not possible, termite activity and/or damage may exist in these areas and nothing in this report implies that any inaccessible or partly inaccessible areas or sections of the property being inspected by me on the date of the inspection were not, or have not been infested by timber pests.

Accordingly, this report is does not report on inaccessible areas. This includes but may not be limited to concealed frame timbers, eaves, areas concealed by concrete floors, wall linings, soil, landscaping, rubbish, floor coverings (carpet lino etc.), Furniture, pictures, appliances (dishwashers, refrigerators, washing machines, ovens, microwave ovens, heating and cooling units etc.), Stored items (clothes on floor, boxes on floor and against walls, beds against walls and the like), insulation, hollow blocks/columns/posts/poles or other architectural hollow structures. Furnishings found at this dwelling were not inspected and do not form part of this inspection.

Summary Only

Important Disclaimer

Important disclaimer

This summary and the opinion is supplied to allow a quick and superficial overview of the inspection results. This summary is not the report and cannot be relied upon on its own. This summary must be read in conjunction with the full report and not in isolation from the report. If there should happen to be any discrepancy between anything in the report and anything in this summary, the information in the report shall override that in this summary. The report is subject to terms and limitations.

Note: It is essential that you read the entire report; other inspectors may have and are entitled to different opinions in relation to this dwelling.

Note: This report should not be relied upon if the contract for sale becomes binding more than 30 days after the date of initial inspection. A re-inspection after this time is essential

1.2 Timber Pest Activity

Was there any Termite Workings or Damage Found

No: Of the areas able to be inspected there were no termite workings or termite damage visible. Please read this report in its entirety.

Were Any Live or Active Termites Found

No: Please read this report in its entirety

NOTE

Note: Any evidence of termite activity or workings in the grounds or building structure assumes that there is risk of termite activity to the main structure. We strongly recommend a treatment to eradicate the termites and to protect the Dwelling

Any Visible Borer of seasoned Timbers Found

No: Please read this report in its entirety.

Any Damage caused by Wood Decay, Rot Found

No: Please read this report in its

Evidence Of Chemical Delignification

No: Please read this report in its entirety.

NOTE

For complete and accurate information please refer to the attached complete visual timber pest report, provided in accord with as 4349.3

Where any major safety hazards identified

No: Please read this report in its entirety.

Susceptibility of this property to timber pests

In our opinion, the susceptibility of this property to timber pests is considered to **HIGH**. Read the report in full.

1.3 Brief Description of the Structure Inspected**Building Type**

Refer To Details In The Building Inspection Report

Terms and Limitations**Important Information**

Any person who relies upon the contents of this report does so acknowledging that the following clauses, which define the scope and limitations of the inspection, form an integral part of the report.

1. This is a visual inspection only in accord with the requirements of as 4349.3 Inspection of buildings part 3: Timber pest inspections. This visual inspection was limited to those areas and sections of the property to which reasonable access (see definition) was both available and permitted on the date of inspection. The inspection did not include breaking apart, dismantling, removing or moving objects including, but not limited to, foliage, mouldings, roof insulation/sisalation, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances or personal possessions. The inspector cannot see inside walls, between floors, inside skillion roofing, inside the eaves, behind stored goods in cupboards, in other areas that are concealed or obstructed. The inspector did not dig, gouge, force or perform any other invasive procedures. An invasive inspection will not be performed unless a separate contract is entered into. In an occupied property it must be understood that furnishings or household items may be concealing evidence of timber pests, which may only be revealed when the items are moved or removed. In the case of strata type properties only the interior of the unit is inspected.

2. Scope of report: This report is confined to reporting on the discovery, or non-discovery, of infestation and/or damage caused by subterranean and dampwood termites (white ants), borers of seasoned timber and wood decay fungi (hereinafter referred to as "timber pests"), present on the date of the inspection. The inspection did not cover any other pests and this report does not comment on them. Dry wood termites (family: Kalotermitidae) and European house borer (*hylotrupes bujulus* Linnaeus) were excluded from the inspection, but have been reported on if, in the course of the inspection, any visual evidence of infestation happened to be found. If *cryptotermes brevis* (West Indian dry wood termite) or *hylotrupes bujulus* Linnaeus are discovered we are required by law to notify government authorities. If reported a special purpose report may be necessary.

3. Hidden damage: If timber pest activity and/or damage is found, within the structures then damage may exist in concealed areas, eg framing timbers. An invasive inspection is strongly recommended in this case. Damage may only be found when wall linings, cladding or insulation are removed to reveal previously concealed timbers.

4. Accesibility: A further inspection is strongly recommended of those areas that were not readily accessible and of inaccessible or obstructed areas once access has been provided or the obstruction removed. At the request of the named client on this report and with the written consent of the vendor, we will revisit the site and re-Inspect the obstructed Areas at a cost to you.

5. Limitations: Nothing contained in the report implies that any inaccessible or partly inaccessible areas or sections of the property being inspected by the inspector on the date of the inspection were not, or have not been, infested by timber pests. Accordingly this report is not a guarantee that an infestation and/or damage does not exist in any inaccessible or partly inaccessible areas or sections of the property. Nor is it a guarantee that a future infestation of timber pests will not occur or be found.

6. Determining extent of damage: The report is not a structural damage report. Any observations or recommendations about timber damage should not be taken as expert opinion and cannot be relied upon. The report will not state the full extent of any timber pest damage. This information is not the opinion of an expert. If any evidence of timber pest activity and/or damage resulting from timber pest activity is reported either in the structure(s) or the grounds of the property, then you must assume that there may be concealed structural damage within the building(s). This concealed damage may only be found when wall linings, cladding or insulation is removed to reveal previously concealed timbers. An invasive timber pest inspection (for which a separate contract is required) is strongly recommended and you should arrange for a separate inspection by a qualified builder, engineer, or architect to carry out a structural inspection and to determine the full extent of the damage and the extent of repairs that may be required. You agree that either we or the individual conducting the inspection is not responsible or liable for the repair of any damage whether disclosed by the report or not.

7. Mould: Mildew and non-wood decay fungi is commonly known as mould and is not considered a timber pest. However, mould and their spores may cause health problems or allergic reactions such as asthma and dermatitis in some people. No inspection for mould was carried out at the property and no report on the presence or absence of mould is provided. If mould is noted as present within the property and you are concerned as to the possible health risk resulting from its presence then you should seek advice from your local council, state or commonwealth government health department or a qualified expert such as an industry hygienist.

8. Disclaimer of liability: No liability shall be accepted on account of failure of the report to notify any termite activity and/or damage present at or prior to the date of the report in any areas(s) or section(s) of the subject property physically inaccessible for inspection, or to which access for inspection is denied by or to the licensed inspector (including but not limited to any area(s) or section(s) so specified by the report).

9. Disclaimer of liability to third parties: Compensation will only be payable for losses arising in contract or tort sustained by the client named on the front of this report. Any third party acting or relying on this report, in whole or in part, does so entirely at his or her own risk.

10. Complaints procedure: In the event of any dispute or claim arising out of, or relating to the inspection or the report, you must notify us as soon as possible of the dispute or claim by email, fax or mail. You must allow us (which includes persons nominated by us) to visit the property (which visit must occur within twenty eight (28) days of your notification to us) and give us full access in order that we may fully investigate the complaint. You will be provided with a written response to your dispute or claim within twenty eight (28) days of the date of the inspection.

11. Complaint investigation: In the event any litigation is started as a result of the inspection and/or report, you indemnify us against any legal fees and expenses incurred where you have not first allowed us the opportunity to visit the property to investigate the complaint and provide you with a written response within 28 days

2. Visual Timber Pest Inspection Report

Important Information

For complete and accurate information please refer to the attached complete visual timber pest report, provided in accord with AS 4349.3

2.1 Brief Description of Areas Inspected

NOTE

Only structures, fences & or trees within 30m of the building but within the property boundaries were inspected.

The areas inspected were

Please refer to the Inspected and restricted areas in the Building Inspection section of this report.

2.2 Areas Not Inspected

Please Note

No inspection was made, and no report is submitted, of inaccessible areas. These include, but may not be limited to, cavity walls, concealed frame timbers, eaves, flat roofs, fully enclosed patios sub-floors, soil concealed by concrete floors, fireplace hearths, wall linings, landscaping, rubbish, floor coverings, furniture, pictures, appliances, stored items, insulation, hollow blocks/posts, etc.

The inspection did not include obstructed areas, not readily accessible and inaccessible areas at the time in inspection which were inaccessible, not readily accessible or obstructed areas at the time of inspection. Locked and restricted areas were not inspected. Removing furnishings and obstructions which may be concealing evidence of defects is outside the scope of this inspection. It is strongly recommended that all obstructions be removed and full access be provided as defects may exist in these areas.

Unable to Inspect

Please refer to the Inspected and restricted areas in the Building Inspection section of this report.



20). TIMBER PEST FINDINGS

3. Subterranean Termites

Were Active or Live Termites Visible

No. Of the visible and accessible areas inspected, there were no visible termites found at the time of the inspection.

3.2 Subterranean Termite Damage or workings

Any workings or damage found

No. Of the visible and accessible areas inspected, no termite working or timber damage found at the time of the inspection.

Was any evidence of timber damage visible to the main Building

No

Where evidence of termite activity or damage has been reported to the building then you must have a building expert determine the full extent of damage and the estimated cost of repairs or timber replacement (See Terms & Limitations).

If damage is visible does it present a safety risk

Important Note: Where a Major Safety Hazard is identified above, it must be attended to and/or rectified to avoid the possibility of personal injury &/or death.

VERY Important:

If live termites or any evidence of termite workings or damage was reported above within the building(s) or in the ground and fences then it must be assumed that there may be concealed termite activity and/or timber damage. This concealed activity or damage may only be found when alterations are carried out such as when wall linings, cladding or insulation are removed or if you arrange for an invasive inspection. We claim no expertise in structural engineering or building. We strongly recommend that you have a qualified person such as a Builder, Engineer, Architect or other qualified expert in the building trade determine the full extent of the damage, if any. This may require an invasive inspection. We take no responsibility for the repair of any damage whether disclosed by this report or not. (See Terms & Limitations).

Where visual evidence of termite workings and/or damage is reported above, but no live termites were present at the time of inspection, you must realize that it is possible that termites are still active in the immediate vicinity and the termites may continue to cause further damage. It is not possible, without benefit of further investigation and a number of inspections over a period of time, to ascertain whether any infestation is active or inactive. Active termites may simply have not been present at the time of inspection due to a prior disturbance, climatic conditions, or they may have been utilizing an alternative feeding source. Continued, regular, inspections are essential. Unless written evidence of a termite protection program in accord with "Australian Standard 3660" with ongoing inspections is provided, you must arrange for a treatment in accord with "Australian Standard 3660" to be carried out immediately to reduce the risk of further attack.

General remarks: Where any current visible evidence of Timber Pest activity is found it is strongly recommended that a more INVASIVE INSPECTION is performed. During the inspection Trees and stumps on the property with a diameter more than 100mm have been visually inspected for evidence of termite activity to a height of 2m where access was possible and practical and trees were no further than 30 meters from the main dwelling. It is very difficult, and generally impossible to locate termite nests since they are underground and evidence in trees is usually well concealed. We therefore strongly recommend that you arrange to have trees test drilled for evidence of termite nests.

Note

Where evidence of termite activity was found in the grounds then the risk to buildings is high unless otherwise specified. A treatment to eradicate any live termites and to protect the building(s) should be carried out. Where the evidence of termite workings was found in the grounds or the building(s) then the risk of a further attack is high unless otherwise specified.

3.3 Any Evidence of a Previous Termite Treatment**Note**

Warning: **IF** evidence of drill holes in concrete or brickwork or other signs of a possible previous treatment are reported then the treatment may have been carried out because of an active termite attack. Recommend obtaining all documentation from the company that did the treatment and also documentation from the contractor for any repairs carried out to determine the extent of any damage repaired or that requires repairing. Normally if a termite treatment has been carried out then a durable notice should be located in the meter box indicating the type of termite shield system, treated zone or combination that has been installed.



21). CONDUCTIVE CONDITIONS

4.2 Moisture Readings

Note


IF any High moisture readings were recorded this can be caused by any one of the following: Poor ventilation, ineffective drainage, leaking pipes, leaking roofs, leaking showers, defective flashing or by concealed termite activity. High moisture is conducive to termite activity.

ANY areas of high moisture should be investigated by way of an invasive inspection. IF high moisture was reported then you must have a building expert investigate the cause of the moisture and if hidden decay or termite activity or damage is present. Seek further assistance from a licensed contractor

6. Other conducive conditions for termite activity

Garden beds/ mulch/ plants

There is mulch and/ or garden beds/ plants located close to the house. These garden beds provide conducive conditions for termites to nest. These garden beds should be removed or relocated further away from the house. The degree of risk is moderate to high.



Stored timber subfloor or external walls

Timber or debris in contact with ground located in sub floor and/or close to external walls. This provides conducive conditions for termite infestation. The degree of risk is high. Remove all Timbers and debris.



Other conducive conditions

Any tree roots hard enough against the house provides conducive conditions for termite activity and should be fully removed





22). OVERALL ASSESSMENT

9. Overall Assessment of Property

Please Note

Where or if there has been evidence of live termites or termite damage or termite workings (mudding) found in the building(s) then the risk of a further attack is extremely high. Where evidence of live termites or termite damage or termite workings was found in the grounds but not in the buildings then the risk to buildings must be reported as high to extremely high.

Degree of Risk of Termite Infestation is

The overall degree of risk of timber pest infestation to this property appears to be **HIGH** - See notes below.

The overall degree of risk of timber pest infestation is a subjective assessment by the inspector at the time of the inspection taking into account many factors which include but are in no way limited to location and proximity to bush land and trees, the presence of evidence of timber pest damage or activity close to the inspected structure or within the inspected structure, conducive conditions that raise the potential of timber pest attack such as timbers in contact with soil, inaccessible areas, slab on ground construction etc, or other factors that in the inspectors opinion, raise the risk of future timber pest attack. It should be noted that even if a risk factor is high, this is not meant to deter a purchaser from purchasing the property, it is just to make them aware that increased vigilance is warranted and any recommendations regarding reducing conducive conditions or frequency of inspections should be headed by any property owner. Often, by reducing or eliminating some of the conducive conditions, the risk factor may be lowered.

10. Subterranean Termite Treatment Recommendation

Treatment Recommendation

There was no evidence of a full termite management system to prevent termite attack to the property. Therefore a management program in accordance with AS 3660-2000 to protect against subterranean termites is considered to be: STRONGLY RECOMMENDED.

NOTE. If it was reported that there was any obstructions blocking the (termite barrier visual inspection zone) or slab edge it is recommended to have the area Re inspected once the obstruction has been removed to ensure no termite activity has occurred.

Undetected termite activity or termite damage risk assessment

High

Due to restrictions and obstructions to the this dwelling the level of undetected termite damage or activity is considered **High**. These include, but may not be limited to, cavity walls, concealed frame timbers, eaves, flat roofs, fully enclosed patios sub-floors, soil concealed by concrete floors, fireplace hearths, wall linings, landscaping, rubbish, floor coverings, furniture, pictures, appliances, stored items, insulation, hollow blocks/posts, etc.

Please refer to section 4 of the terms and conditions outlined in this report.

11. Future Inspections

Recommended future Inspection Intervals

Future inspections: As 3660.2-2000 Recommends that inspections be carried out at intervals no greater than annually and where timber pest Risk is greater, this interval should be shortened. Inspections will not stop timber pest infestations; however, the damage which may be caused will be reduced when the infestation is found at an early stage.

Due to the degree of risk of subterranean termite infestation noted above and all other findings of this report, we strongly recommend that a full inspection and written report in accordance with as 4349.3 Or as 3660.2-2000 be conducted as per below.

Every 12 Months.

12. Note

Terms and conditions

IMPORTANT INFORMATION

In relying upon this report you should read and understand the following important information. It will help explain what is involved in a timber pest inspection, the difficulties faced by a timber pest inspector and why it is not possible to guarantee that a property is free of timber pests. It also details important information about what you can do to help protect your property from timber pest attack. This information forms an integral part of the report.

1.0 DEFINITIONS: For the purpose of this inspection, the definitions below apply.

1.1 Active - The presence of live timber pests at the time of inspection.

1.2 Inactive - The absence of live timber pests at the time of inspection.

Note: Where visual evidence of inactive termite workings and/or damage is located, it is possible that termites are still active in the immediate vicinity and the termites may continue to cause further damage. It is not possible, without the benefit of further investigation and inspections over a period of time, to ascertain whether any infestation is active or inactive. Continued, regular inspections are essential.

1.3 Minor - Damage that is superficial and does not appear to require any timber replacement or repairs to be carried out.

1.4 Moderate - Damage that is more than surface damage and it is likely to necessitate timber repairs with possible replacement (if more economical or for aesthetic reasons) to be carried out.

1.5 Severe - Damage that appears to be significant and the integrity or serviceability of timbers may be impaired. Usually timbers will have to be repaired and/or replaced.

1.6 Timber Damage - It is essential that any timber damage noted in the report be referred to a suitably qualified building professional and obtain a special purpose building report relating to the extent of the timber damage. The full extent of damage may only be revealed by invasive inspection methods including probing and the removal of lining materials. This type of invasive inspection has not been carried out and you should understand that the extent and/or severity of timber damage may be found to increase significantly on such an invasive inspection. The references contained within this report that may refer to the extent of timber damage have only been included to assist in determining treatment specifications and not to quantify the damage and must not be relied upon to determine the costs of repair or replacement.

2.0 REASONABLE ACCESS: Only areas where reasonable access was available were inspected. The Australian Standard AS3660 refers to AS4349.3-2010 which defines reasonable access. Access will not be available where there are safety concerns, or obstructions, or the space available is less than the following:

ROOF SPACE - the dimensions of the access hole must be at least 500mm x 400mm, and, reachable by a 3.6M ladder, and, there is at least 600mm x 600mm of space to crawl. **Roof Space Access – only if inspector can turn off power. Queensland Legislation Compliance**-From 1 January 2025, new requirements introduced under Queensland legislation regulate access to domestic roof spaces. Where applicable, the inspector will comply with all relevant safety protocols as mandated by this legislation. If safe access, supervision, or necessary isolation procedures cannot be confirmed or implemented at the time of inspection, entry into the roof space may be refused. The client acknowledges that such access limitations are outside the control of the inspector and the "client/You" agree that **no liability will be accepted for any defects or conditions not visible or accessible due to these legislative restrictions.**

SUBFLOOR - the dimensions of the access hole must be at least 500mm x 400mm and, there is at least 400mm of space to crawl beneath the lowest part of any bearer and at least 500mm below any concrete member.

ROOF EXTERIOR - must be accessible by a 3.6M ladder placed safely on the ground.

Reasonable access does not include the use of destructive or invasive inspection methods. Nor does reasonable access include cutting or making access traps, or moving heavy furniture or stored goods.

3.0 A MORE INVASIVE AND PHYSICAL INSPECTION IS RECOMMENDED: This inspection was a visual inspection only. As detailed above, there are many limitations to this visual inspection. In this case a further invasive inspection is required as damage may only be found when the structure is empty and wall linings, cladding or insulation is removed to reveal previously concealed timbers.

4.0 CONCRETE SLAB HOMES (Part or full slab) Homes constructed on concrete slabs pose special problems with respect to detecting termite attack. If the edge of the slab is concealed by garden beds, lawns, paths, pavers or any other obstructions then it is possible for termites to effect concealed entry into the property. They can then cause extensive damage to concealed framing timbers before being detected. Even the most experienced inspector may be unable to detect their presence due to concealment by wall linings or other obstructions. Only when the termites attack timbers in the roof void, which may be concealed by insulation, or some other visible timbers, can their presence be detected. Where termite damage is located in the roof it should be expected that concealed framing timbers (if present) may be extensively damaged. With a concrete slab home (part or full) it is imperative that you expose the edge of the slab. This may involve the excavation of soil or the complete removal of garden beds, paths, pavers or other features which concealed the slab edge. It is recommended that at least 75 millimetres of the slab edge above ground level remain exposed at all times to facilitate the detection of termite entry. Weep holes must also be kept free of obstructions at all times.

5.0 EVIDENCE OF TERMITE DAMAGE: Where evidence of termite damage was noted in any structure or on the grounds of the property, you must understand that termite damage or activity may exist in concealed areas. Termites are secretive by nature and they will often temporarily desert their workings to later return. As damage or activity may exist in concealed or inaccessible areas, a further **INVASIVE INSPECTION** is strongly recommended, see Section 3.0 - Further Invasive Inspections. Additionally, regular inspections are strongly recommended at intervals not exceeding 12 monthly and more frequently if recommended.

6.0 SUBTERRANEAN TERMITES: No Property is safe from termites! Termites are the cause of the greatest economic losses of timber in service in Australia. Independent data compiled by State Forests shows 1 in every 4 homes are attacked by termites at some stage in their life. Australia's subterranean termite species are the most destructive timber pests in the world.

How termites attack your home! The most destructive species live in large underground nests containing several hundred thousand timber-destroying insects. The problem arises when a nest matures near your home. Your home provides natural shelter and a food source for the termites. The gallery system of a single termite colony may exploit food sources over as much as one hectare, with individual galleries extending up to 50 metres or more to enter your home. Concrete slabs do not act as a barrier as termites can penetrate cracks through the slab or over the slab edge and once in contact with the timber they can excavate it often leaving only a thin veneer on the outside. If left undiscovered the economic species can cause many thousands of dollars damage and can be costly to treat.

7.0 BORERS OF DRY SEASONED TIMBERS: Borers are the larval stage of various species of beetle. The adult beetles lay their eggs within the timber. The eggs hatch out into larvae that bore through the timber. The larvae may reside totally concealed within the timber for a period of several years before passing into a dormant pupal stage. Within the pupal case they metamorphose (change) into the adult beetle that cuts a hole in the outer surface of the timber to emerge, mate and lay further eggs to continue the cycle. It is only through the presence of these emergence holes that their presence can be detected. Refer to this report (if applicable) for further information.

Anobium punctatum borer (furniture beetle). Commonly attack softwood flooring timbers, shelving timbers and timber panelling. They have the potential to cause severe timber damage if left untreated for many years. Attack by this beetle is usually observed in timbers that have been in service for 10 to 20 years or more.

Lyctus brunneus borer (powder post beetle). These borers only attack the sapwood of certain susceptible species of hardwood timber. Since it is a requirement that the structural timbers contain no more than 25% *Lyctus* susceptible sapwood, these borers are not normally associated with structural damage. Replacement of affected timbers is not recommended and treatment is not approved or required.

Queensland Pine Beetle borer. These borers commonly attack flooring and wall timbers. It is not possible to determine with absolute certainty whether activity exists without destruction of the timbers. We therefore recommend that it would be prudent to assume that current borer activity is present unless written evidence is available to indicate that the property has been recently treated in respect to this borer. Replacement of affected timbers is always preferred as a long term solution since, in the event of selling the property in the future it is probable that an Inspector will report the borers as active (see above). A chemical treatment to control re-infestation may be considered a less effective and lower cost option. This treatment is applied to the underside of all soft pine flooring timbers and to other affected timbers as required.

Non-Commercial borers Are those borers that attack dead trees, logs and tree stumps. These borers are generally not considered to be a threat to timber in service (timber used in the buildings). No treatment is necessary for this species.

8.0 FUNGAL DECAY (WOOD ROT) Fungal decay is more commonly known as wood rot. Many problems with timber pests are related to excessive moisture because Termites and wood rot both require heat and moisture to survive. Small sections of minor decay can often be removed and the resulting hole filled with "Builders filler".

Areas of moderate decay will require sections of timber to be replaced. Where there is severe fungal decay the entire affected timber member should be replaced, preferably with treated hardwood.

Oregon timber is highly susceptible to Fungal Decay and should be kept well painted. Oregon was once used extensively to construct pergolas and carports and the like. The use of Oregon in external applications is generally considered to be unsuitable.

9.0 MOULD: Mildew and non-wood decay fungi is commonly known as Mould and is not considered to be a timber pest. However, Mould and their spores may cause health and allergic reactions such as asthma and dermatitis in some people. No inspection for Mould was carried out at the property and no report on the presence or absence of Mould is provided.

If Mould is noted as present within the property and you are concerned as to the possible health risk resulting from its presence then you should seek advice from your Local Council, State or Commonwealth Health Department or a qualified expert such as an Industry Hygienist.

10.0 COMPLAINTS PROCEDURE: In the event of a dispute or a claim arising out of, or relating to the Inspection or the Report, You must notify Us as soon as possible of the dispute or claim by email, fax or mail. You must allow Us (which includes persons nominated by Us) to visit the property (which visit must occur within twenty eight (28) days of your notification to Us) and give Us full access in order that We may fully investigate the complaint. You will be provided with a written response to your dispute or claim within (28) days of the date of the inspection.

CONTACT THE INSPECTOR: Please feel free to contact the inspector who carried out this inspection. Often it is very difficult to fully explain situations, problems, access difficulties, building faults, timber pest activity and damage or their importance in a manner that is readily understandable by the reader. Should you have any difficulty in understanding anything contained within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require clarification then contact the inspector prior to acting on this report.

The Inspection and Report was carried out by: Greg Palmer
State License Number: QBCC 1284560 Qld pmt1007100918
Contact the Inspector on: 0478181208
For and on Behalf of: Profile building and pest inspections

